

Surface Mounted

Installation Instructions

De-energize circuit before installation.

1. Mounting bracket to be mounted only on 4" octagonal j-boxes. Feed wiring through threaded center of mounting bracket.
2. J-Box (J-Box and mounting hardware supplied by others) for use with 3-1/2" and 4" octagonal recessed junction boxes with 2-3/4" mounting hole spacing. (Appropriate device ring cover may required and to be supplied by others.)
3. Raise product and connect primary voltage supply to the line and neutral leads of the fixture. Refer to product label for required input voltage.
4. Properly ground mounting bracket in accordance with all local and national electrical codes.
5. Return wires through mounting bracket and into the j-box.
6. Secure fixture to mounting bracket via the supplied mounting screws.
7. Energize circuit and test for proper operation.

