


CALVIN22 Bollard Color Chart

Traditional Standard Paint Colors



RAL Custom Color (Consult Factory- MOQ Required)

There are 5 finishing stages in the finishing process for proper protection and durability

Stage 1: Heat treat aluminum parts to yield strength - not all applications require heat treat process

Stage 2: All aluminum parts are degreased using cleaning agent before going through an industurial detergent rinse

Stage 3: Product enters a four step iron phosphate coating treatment to prepare metal for powder coating

- -Iron Phosphate Bath
 - -Clean cold rinse
 - -Clean hot rinse
 - -High pressure air drying to insure all water is absolved for final stage

Stage 4: Powder coating application onto raw/clean parts before curing

Stage 5: Product cures in our industrial oven set to required temperature for final process of application

-Note: All colors shown are approximate and may have slight variation on actual product